


D011 LUX METER MODULE

LUX Meter Module kit has been design to measure the illumination. Illumination is luminas flux falling on surface area of photo diode. This illumination converted to corresponding voltage using Op-Amp circuit.

- Supply 9 VDC PP3 Battery @ 20 mA
- Onboard Photo Diode
- Onboard preset for calibration
- Range selection via jumper 10mV/LUX, 1mV/LUX, 0.1mV/LUX
- Interfacing is via berg connector
- Power-On LED indicator
- Four mounting holes of 3.2 mm each
- PCB dimensions 53 mm x 38 mm





The kit is designed around Texas instrument Op-Amp TLC271 which can operate from single supply with low bias current, here op-amp act as current to voltage converter. 5000 LUX (approx) can be measure with a voltmeter having 5V range. Meter is not provided.

Calibration

- J1 Jumper : 10mV/Lux
- J2 Jumper : 1mV/Lux
- J3 Jumper : 0.1mV/LUX
- PR2 Preset : For Calibrate the meter
- PR1 Preset : Fine Gain adjustment for 10mV/Lux
- CN1 Connector : Supply 9 VDC (PP3 9V DC Battery Ideal) and Output Voltage
- D2 LED : Power Indicator
- D1 LED : Photo Diode (Sensor)

Standard incandescent 100W lamp should be used for approximation calibration. To make Calibration select the 1mV/Lux J2 Jumper, move the preset full in CCW. Connect the accurate voltmeter having range of 5V. Adjust the distance between the photo diode and Lamp so that voltmeter reads 0.38V0. At this point, illumination on photodiode surface is about 100 Lux (aprox). And then adjust the PR2 so that voltmeter reads 1V. Calibration is now been complete.



SR.	QTY.	REF.	DESCRIPTION
1	1	CN1	4 PIN BERG CONNECTOR
2	1	C1	100pF
3	1	C2	0.1uF
4	1	C3	10uF/63V OR 50V
5	1	C4	220pF
6	1	D1	PHOTODIODE
7	1	D2	RED LED
8	3	J1,J2,J3	2 PIN JUMPER
9	1	PR1	1M PRESET
10	1	PR2	470E/500E PRESET
11	3	R1,R4,R5	1K
12	1	R2	100K
13	1	R3	10K
14	1	U1	TLC271
15	1	SOCKET	8 PIN DIP IC SOCKET
16	1	JC02	JUMPER CLOSER

